

Description		Total
SCOPE OF WORK		5,500.00
Replace screws located in coping		
Remove worn caulking at coping laps and reseal with new		
Remove drain strainer, loosen clamping ring seal between single-ply and drain bowl with water block mastic		
Repair voids found at skylight flashings and corners		
Please sign this estimate below in agreement of the price stated and your understanding of the scope of work that will be performed. Signed: _____ Date: _____		
ESTIMATES ARE VALID FOR THIRTY (30) DAYS		Total \$5,500.00



