



03/08/16

Chief Darby City of Foley

jdarby@cityoffoley.org

**Reading 8' Service Body for 3/4 Ton
Single Rear Wheel 56" CA**

Reading Classic II Service Body

Powdercoat White Body Inside and Out

Split Bumper For Liftgate

LED Stop Tail and Turn Lights

Fully Installed

Total Body and Equipment

UNITS	COST	EXT. COST
		\$0.00
		\$0.00
		\$0.00
1	\$5,985.00	\$5,985.00
		\$5,985.00

Reading 98 ClassicII Service Body

Flip Top Lids Spacemaker Body

Powdercoated White Inside and Out

Step Bumper

LED Stop Tail and Turn Lights

		\$0.00
1	\$6,375.00	\$6,375.00
		\$0.00
		\$0.00
		\$0.00
		\$6,585.00

Reading Standard Line Body

Similar To Classic II

Standard Door Hinges

Paddle Latches Instead Of Automotive Style

Powdercoat White

1	\$5,675.00	\$5,675.00
		\$0.00
		\$0.00
		\$0.00
		\$5,675.00

Other Options:

Credit for pickup bed

Angular Side Mount Ladder Rack

Full Overhead Material Rack

Trailer Hitch, Elec Plug Chain Eyes

1	\$500.00
1	\$475.00
1	\$1,150.00
1	\$475.00